

Stela

Catenary Mounting Installation Instructions

STRUCTURA

Warnings

CAUTION—risk of fire and this product must be installed in accordance with the applicable installation code by a person familiar with the construction and operation of the product and the hazards involved.

Suitable for wet locations.

Mounting orientation must have light source facing down.

Electrical service must be disconnected during installation.

Proper grounding is required to protect against shock and proper operation.

Tools Required

7/16" socket wrench
9/64" Allen wrench
5/64" Allen wrench
Wiring tools and connectors

Installation

Step 1: Turn off power to location.

Step 2: Attach fixture mounting bracket to fixture as shown in Figure A using supplied 1/4"-20 hex head bolts.

Step 3: Set cable support bracket in mounting bracket, hold up to catenary cable, and cover with cable clamp and bracket cover.

Step 4: Secure brackets with supplied clevis pin. Tighten (2) 8-32 socket cap screws to clamp onto catenary cable as shown in Figure C.

Step 5: Plug power feed connector to infeed connector. The IP67 connectors align via molded in alignment marker. Secure plugs together by screwing central pieces.

Step 6: Turn power back on to location.

